



Paradise Home Check LLC  
P.O. Box 8635  
Naples, FL 34101  
paradisehomecheck@gmail.com  
239-877-6218

# Wind Mitigation Inspection Report



Fairways at Par 5  
4233 27th Ave SW.  
Naples, FL 34116

# Paradise Home Check LLC

11:44 September 05, 2019

Page 1 of 4  
4233 27th Ct. SW.alb6



**#1 East View**




**#2 South View**



**#3 West View**



**#4 North View**



**#5 Front Entry Door Example**



**#6 Rear Entry Door  
Impact**



# Paradise Home Check LLC

11:44 September 05, 2019

Page 2 of 4  
4233 27th Ct. SW.alb6



**#7 Rear Entry Door  
Glass Etch**




**#8 Rear Entry Door  
Wind Label #1**




**#9 Rear Entry Door  
Wind Label #2**



**#10 Window Example #1  
Impact**



**#11 Window Example #2  
Impact**



**#12 Window Example #3  
Impact**



#13 Window Wind Label #1



#14 Window Wind Label #2



#15 2x4 Trusses



#16 SWR See Permit



#17 Plywood 1/2" Thick



#18 Trusses Spaced 24" OC



# Paradise Home Check LLC

11:44 September 05, 2019

Page 4 of 4  
4233 27th Ct. SW.alb6




**#19 8 D Nails**



**#20 Zircon Locating Tool**



**#21 8 D Nails Spaced 6" OC**



**#22 Clips with 4 Nails**