



Paradise Home Check LLC
P.O. Box 8635
Naples, FL 34101
paradisehomecheck@gmail.com
239-877-6218

Wind Mitigation Inspection Report



Fairways at Par 5
4239 27th Ct. SW
Naples, FL 34116

Paradise Home Check LLC

15:32 August 21, 2019

Page 1 of 4
4239 27th Ct.alb6



#1 East View



#2 South View



#3 West View



#4 North View



#5 Front Entry Door Example



**#6 Rear Entry Door
Impact**

Paradise Home Check LLC

15:33 August 21, 2019

Page 2 of 4
4239 27th Ct.alb6



**#7 Rear Entry Door
Wind Label #1**




**#8 Rear Entry Door
Wind Label #2**



**#9 Rear Entry Door
Glass Etch**



**#10 Window Example #1
Impact**



**#11 Window Example #2
Impact**



**#12 Window Example #3
Impact**

Page 3 of 4
4239 27th Ct.alb6



Paradise Home Check LLC

15:33 August 21, 2019

Page 4 of 4
4239 27th Ct.alb6




#19 8 D Nails



#20 Zircon locating Tool



#21 8 D Nails Spaced 6" OC



#22 Clip with Multiple Nails