



Paradise Home Check LLC  
P.O. Box 8635  
Naples, FL 34101  
paradisehomecheck@gmail.com  
239-877-6218

# Wind Mitigation Inspection Report



Fairways at Par 5  
4245 27th Ct. SW  
Naples, FL 34116

# Paradise Home Check LLC

12:11 September 05, 2019

Page 1 of 4  
4245 27th Ct. SW.alb6



**#1 East View**



**#2 North View**



**#3 West View**



**#4 South View**



**#5 Front Entry Door Example**



**#6 Rear Entry Door  
Impact**



# Paradise Home Check LLC

12:11 September 05, 2019

Page 2 of 4  
4245 27th Ct. SW.alb6



### #7 Rear Entry Door Wind Label #1



### #8 Rear Entry Door Wind Label #2



### #9 Rear Entry Door Glass Etch



## #10 Window Example #1 Impact




## #11 Window Example #2



### #12 Window Example #3 Impact

Page 3 of 4  
4245 27th Ct. SW.alb6







**#19 8 D Nails (3/4" Plywood)**




**#20 Zircon Locating Tool**



**#21 8 D Nails Spaced 6 OC**



**#22 Clips with 4 Nails**



**#23 Additional Retrofit  
Clips with 4 Screws**