



Paradise Home Check LLC
P.O. Box 8635
Naples, FL 34101
paradisehomecheck@gmail.com
239-877-6218

Wind Mitigation Inspection Report



Fairways at Par 5
4257 27th Ct. SW
Naples, FL 34116

Paradise Home Check LLC

16:07 August 21, 2019

Page 1 of 4
4257 27th Ct. SW.alb6



#1 East View



#2 South View



#3 West View



#4 North View



#5 Front Entry Door Example



**#6 Rear Entry Door
Impact**

Paradise Home Check LLC

16:07 August 21, 2019

Page 2 of 4
4257 27th Ct. SW.alb6



**#7 Rear Entry Door
Glass Etch**



**#8 Rear Entry Door
Wind label #1**




**#9 Rear Entry Door
Wind label #2**



**#10 Window Example #1
Impact**



**#11 Window Example #2
Impact**



**#12 Window Example #3
Impact**



#13 Window Wind Label #1



#14 Window Wind Label #2



#15 2x4 Trusses



#16 SWR See Permit



#17 Trusses Spaced 24" OC



#18 Plywood 3/4" Thick

Paradise Home Check LLC

16:07 August 21, 2019

Page 4 of 4
4257 27th Ct. SW.alb6




#19 8 D Nails



#20 Zircon Locating Tool



#21 8 D Nails Spaced 6" OC



#22 Clips with 5 Nails